

SAFETY OBSERVATION REPORT

Observers: T. Roser, S. LaMontagne, K. Mirabella, E. Lessard		Date: 4/10/08	Duration: 0.75 Hr.	Building 1007		
Observation Categories	Observation Questions:					
POS	In risky position relative to task? Exposed to risks of temperature/electricity/gas/chemicals/radiation? Protection OK?					
ERG	Risks from: posture, repetitive motion, load, vibration, temperature, lighting, noise, work flow?					
PPE	Correct PPE? In safe condition? All parts of the body properly protected?					
T&E	Is tool, equipment or facility right for the job? In safe condition? Used correctly?					
PRO	Is there a standard procedure? Is procedure adequate? Up to date? Understood? Followed?					
ORD	Is workplace orderly? Adequate space? Is there a place for all materials and equipment? All in its place?					
ASF	No unsafe acts or conditions identified					
Work Area or Location	Number of Contacts	Description of unsafe acts	Observation Category	Follow-up Action	Person Responsible	By Date
Building 1007 – Electrical bench work on power amplifiers	3	No unsafe acts observed.	ASF			
		Worker referenced out of date Energized Work Permit	PRO	Improve control of work permits in work areas	D. Bruno	5/1/08
		Positive: Work planning was used. Housekeeping is good. Workers very knowledgeable about hazards and controls. PPE was available.				
		Feedback: 1) No bathroom facilities in building 2) Dust in everything due to unpaved areas around AC intakes 3) Training exam questions could be improved if correct answers were given after grading		1) and 2) - Try to improve facility issues where practicable 3) Send exam feedback to BNL Training	A. Pendzick/J. Sandberg J. Maraviglia	5/15/08 4/21/08
COMMENT:						